



Maersk Feeder – Collision with Thistle Platform

What happened and lessons learned

Robin Critchard
Ben Hammond

29 November 2009

Introduction

- Maersk Feeder
 - Platform Supply Vessel
 - Built: Ulstein Verft A/S, Norway, 1993
 - Propulsion / Manoeuvring:
 - 2 main propellers
 - 2 stern thrusters
 - 1 bow thruster
 - 1 azimuth thruster
 - 2 alternators driven from main engines




Incident Details

3rd May 2009

- 12:48 – Arrive Thistle Alpha platform 500m zone
- 12:51 – 500m checks completed (including thruster test)
- 13:12 – Alongside SW crane (weather side) call ready to commence
- 13:15 – 2nd Officer takes control from Chief Officer
- 13:18 – Discharging potable water

- Weather conditions – SW 8kts / Sea 1.0m





Incident Details

3rd May, 2009 - 14:54

- Low air pressure alarm (port side gearbox)
- Control of vessel retaken by Chief Officer
- Loss of air pressure to port gearbox clutch
 - Loss of port propeller
 - Loss of 2 forward thrusters (azimuth and tunnel)
 - 1 aft thruster
 - Loss of power to emergency switchboard
- Emergency generator auto-starts
 - Power restored to emergency switchboard
 - Auto-start of auxiliary generator restores hotel services
- Deck crew instructed to clear deck
- Stbd propeller moved to ahead to clear platform (bridge thought all thrusters lost)
- Vessel Master arrives on the bridge



Incident Details

→ 14:55

- Contact with platform protruding from Thistle A
- Manoeuvred clear

→ 14:56

- Potable water hose torn off at platform manifold.

→ 14:57

- Vessel moving clear of Thistle A
- Stbd propeller declutched to prevent pot water hose fouling

→ 15:12

- Vessel clear of 500 metre zone

→ 15:18

- Pot water hose recovered to deck

Consequences

- Slight damage to platform
 - Redundant dive control area
- Significant damage to vessel
 - Main mast
 - Communications aerials
- No personal injuries



Causes

→ Immediate Causes


- Failure of Rotoflex coupling seal on port gearbox

→ System causes

- No change out period in maintenance system
- Azimuth locking PLC power loss




Rotoflex Coupling



Technology

- Fitting to connect air line failed
- Gearbox declutches alternator and prop lost
- Fitting had not been replaced
- Not part of maintenance system



Actions

- Vessel crew commended for professional response
- All Rotoflex unit renewed (all F-types)
- Safety Flash issued to Maersk fleet
- Proving trials to Master and charterer satisfaction
- Maintenance system updated
 - Renewal every 3 years (less than manufacturer recommendations)
- 24V – 220V inverter fitted to power Azimuth locking PLC
- Maersk inform ship builders of incident and modifications