



Follow-Up to Safety Flash 06-16

Issued: 9th June 2006

Subject: Dacon Scoop Lifting Rings

The following message was received today by Dacon in response to the problems encountered with their lifting rings:

"As a result of the two incidents reported, Dacon AS has chosen to replace all stainless steel lifting rings on the Dacon Rescue Scoops manufactured after year 2000 when these rings were introduced.

The rings to be replaced are of 90x13mm and 120x13mm.

We ask all users of this equipment to contact Dacon AS for certified replacement rings by e-mail: rescue@dacon.no or fax: +47 67 53 34 40."