



**Marine Safety Forum  
All Members Meeting  
28 May 2009**

## Dropped Objects

**Goose neck (Wt 3 Kg) from SME header tank fell to E/Room lower plates**  
**Threaded pipe section badly corroded - fell from tank down ladder/stairway**



# Dropped Objects



**Nail bar was found by an alert Crewmember as the unit landed.**

**Investigation could not establish who owned the bar – installation, vessel or vendor!**



## Dropped Objects



**Deck Crew on vessel were conducting tank lid work close to the container – AB placed the torch onto the handle while concentrating on another part of the task – and forgot about it. The unit was later lifted to the Installation where it was spotted**



## Dropped Objects



**Whilst working on the vessel's cargo deck a Crewmember spotted a loose metal handle lying on top of a cargo container which had been loaded that morning in Aberdeen. The handle was steel approx nine inches long weighing approx 250 grams**



## Dropped Objects

- 1/ AB noticed this object fall from a tank after the tank had landed on deck
- 2/ As a tank was being back loaded on to the vessel, it struck another tank and the clamp fell from the top to the deck

1/



2/



## Dropped Objects

- The welding rods came down from a Platform in SNS
- Working gloves – from shore Crew in GY - were spotted by Crew doing pre-departure checks





**Marine Safety Forum  
All Members Meeting  
28 May 2009**